

2017 Toyota ROOMY Custom G-T		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-M900A	996 cc		
YEAR / REG.	MILEAGE		
2017/11	76,520 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900A-0121476	372 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Pre-Collision Braking		Cruise Control	
Back Camera		Navigation System	
INSPECTOR REPORT			
Left front pillar dented, Front support bent, Left front fender stay distorted, Left headlight stay cracked, Rear gate trim partially cracked.			

ORIGINAL JAPANESE AUCTION SHEET

型式 H29 11月	メーカー トヨタ	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 3
車種 乗用車・その他 ()	グレード ルーミー カスタム G-T	排気量 1000 cc	型式 DBA-M900A	駆動方式 A・B・C
年 76	月 520	日 0	燃料 ガソリン	ディーゼル
走行 76,520 km	インパネ	CVT	後部座席 3人	乗客定員 5人
外装色 ブルー	カラーNo. AG・AGD・WAG ()	エンジン 1.0L	変速機 AT	サドル
内装色 ()	内装 ()	タイヤ 155/65R13	ホイール 155/65R13	タイヤ 155/65R13
セーリングポイント	ターボ 両側パワースライドドア 純正9インチナビ クルーズコントロール LEDヘッドライト	修復歴 有・無	修復歴 有・無	修復歴 有・無
検査記入欄	左フビラ凹み Fサボート曲がり 左フエグダステー歪 左ヘッドライトステー割れ Rゲートトリム1部割れ	左フビラ凹み Fサボート曲がり 左フエグダステー歪 左ヘッドライトステー割れ Rゲートトリム1部割れ	左フビラ凹み Fサボート曲がり 左フエグダステー歪 左ヘッドライトステー割れ Rゲートトリム1部割れ	左フビラ凹み Fサボート曲がり 左フエグダステー歪 左ヘッドライトステー割れ Rゲートトリム1部割れ
車検 M900A-0121476	車検 M900A-0121476	車検 M900A-0121476	車検 M900A-0121476	車検 M900A-0121476
車検 M900A-0121476	車検 M900A-0121476	車検 M900A-0121476	車検 M900A-0121476	車検 M900A-0121476