


2017 Toyota TANK Custom G_S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-M900A	996 cc		
YEAR / REG.	MILEAGE		
2017/05	53,200 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900A-0060029	373 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Pre-Collision Braking		Cruise Control	
Back Camera		Navigation System	
INSPECTOR REPORT			
Exterior condition is AU (minor imperfections).			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29 5月	メーカー トヨタ 車名 タンク	ドア枚数 5 グレード カスタムG_S	ボディ形状 コンパクトハッチバック	評価点 4
車種 自家用・その他 ()	排気量 1000 cc	型式 DBA-M900A	変換形式	内装 A・⑤・C
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼルの ハイブリッド ()	後日選り込み (保証書・取扱説明書等)	
走行 53,200 km	シフト AT			
外装色 パールホワイトIII	カラーNo. ()	④D・AAG・WAG・()	新着品のみ O印 を記入	
内装色 ()	乗車定員 5人	⑤	⑥	⑦ サンルーフ ⑧ 革シート
⑨ 左・⑩ 右 ⑪ 輸入車 ⑫ ディーラー車 ⑬ 走行	⑭ サイクル数 9,130円	⑮ ⑯ ⑰ ⑱ ⑲	⑳	㉑ ス
セールスポイント 社外ナビ/衝突安全装置/両側電動スライドドア/車線逸脱 防止支援システム/ドライブレコーダー 社外/Bluetooth接 続/ETC/BD付ABS/横滑り防止装置				
検査記入欄		修復歴 有・⑤		
外装AU		A キズ U ヘコみサシキ B キズヘコみ P 色あせサシキ Q ガラスキズ W 経年劣化 S サビ C 腐食 X 交換部 XX 交換済 登録No. 月 日 までに名義できる方 車体番号 M900A-0060029		
① ② ③ ④ フレ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑		