

2017 Toyota TANK Custom G-T		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-M900A	996 cc		
YEAR / REG.	MILEAGE		
2017/09	56,400 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900A-0101084	373 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Pre-Collision Braking		Cruise Control	
Back Camera		Navigation System	
INSPECTOR REPORT			

初年度登録	メーカー	トヨタ	ドア枚数	5	ボディ形状	コンパクトハッチバック	評価点																																							
H29 / 9月	車名	タンク	グレード	カスタムG-T	駆動方式	2WD 4WD	4																																							
車庫	自家用・その他 ()	排気量	1000	型式	DBA-M900A	選装形式	内装	A・B・C																																						
車検	8年9月 / 抜消	燃料	ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)																																									
走行	56,400 km	シフト	AT	☐ 2WD ☐ 4WD																																										
外装色	カラーNo.	エアコン	☒ A・AAG・WAG・()																																											
レーザブルークリスタルシヤイン	()	内装色	標準定員	5人	☒ 革シート ☐ ミニストップ																																									
左・右・後入れ	ディーラー・並行	リサイクル料	9,130円	買付額	☒ エアパック ☐ ABS ☐ 安全ブレーキ ☐ 安全ガラス																																									
セールスポイント																																														
純正9インチナビゲーション・純正12.1インチスマートフォンアシスト (トヨタ・ナビゲーション) 両側電動スライドドア・車線逸脱防止支援システム																																														
検査記入欄																																														
外装AU																																														
<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘコみ・割れ</td> <td>B</td> <td>キズ・ヘコみ</td> <td>C</td> <td>色あせ・汚れ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>修繕跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換品</td> <td>XX</td> <td>交換済</td> </tr> <tr> <td colspan="9"> 登録No. _____ 月 _____ 日 _____ までで名義できる方 </td> </tr> <tr> <td colspan="9"> 車体番号 M900A-0101084 </td> </tr> </table>									A	キズ	U	ヘコみ・割れ	B	キズ・ヘコみ	C	色あせ・汚れ	G	ガラスキズ	W	修繕跡	S	サビ	C	腐食	X	交換品	XX	交換済	登録No. _____ 月 _____ 日 _____ までで名義できる方									車体番号 M900A-0101084								
A	キズ	U	ヘコみ・割れ	B	キズ・ヘコみ	C	色あせ・汚れ	G	ガラスキズ																																					
W	修繕跡	S	サビ	C	腐食	X	交換品	XX	交換済																																					
登録No. _____ 月 _____ 日 _____ までで名義できる方																																														
車体番号 M900A-0101084																																														
<table border="1"> <tr> <td>PW</td> <td>70km/h</td> <td>70km/h</td> <td>ワレ</td> <td>外装</td> <td>小</td> <td>中</td> <td>大</td> <td>エアロ</td> <td>シリアル</td> </tr> <tr> <td>内装</td> <td>70km/h</td> <td>70km/h</td> <td>ワレ</td> <td>外装</td> <td>小</td> <td>中</td> <td>大</td> <td>エアロ</td> <td>シリアル</td> </tr> </table>									PW	70km/h	70km/h	ワレ	外装	小	中	大	エアロ	シリアル	内装	70km/h	70km/h	ワレ	外装	小	中	大	エアロ	シリアル																		
PW	70km/h	70km/h	ワレ	外装	小	中	大	エアロ	シリアル																																					
内装	70km/h	70km/h	ワレ	外装	小	中	大	エアロ	シリアル																																					