

2017 Volkswagen VW Polo 5HB TSI Comfortline Meister		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-6RCJZ	DISPLACEMENT 1,197 cc		
YEAR / REG. 2017/07	MILEAGE 33,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. WVWZZZ6RZHU075109	DIMENSIONS (L X W X H) 400 × 169 × 147 cm		
SALES POINTS			
Alloy Wheels Back Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
AIS inspected. Oil seepage around the engine. Minor scratch/dent (A) on the front bumper underside. Air bubbles on the edge of the front glass. Headlights are cloudy/hazy.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H29/7月	メーカー フォルクスワーゲン	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 ポロ	グレード TSIコンフォートラインマイスター	駆動方式 4WD	燃費区分 4WD	
車種 自家用・その他()	排気量 1190 cc	型式 DBA-6RCJZ	燃費 A・B・C	
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (取替・取替不可等)	
走行 33,000 km	フロア 7 AT			
外装色 レッド	カラーNo. AG・AG・WAG・()	エアコン	新着品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ	高シート	
小回り 左・右	走行 14,270 km	エレクトロニック	TV	ナビ
セールスポイント				
キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/メモリーナビ他ETC/盗難防止システム/横滑り防止装置(ESC)/CD/バックカメラ/定期点検記録簿				
検査記入欄				
ABS検査済/エンジン廻りオイル漏み/バンパー下面A有/Fガラスふち気泡/ヘッドライトくもり				
車体番号 WVWZZZ6RZHU075109				
FW トボ石	備A シシ	フレ ヤブレ	外装 コガ	小 コガ
内装 コガ	シシ	ヤブレ	コガ	コガ
エアロ シリアル No.	エアロ シリアル No.	エアロ シリアル No.	エアロ シリアル No.	エアロ シリアル No.
重量 cm	重量 cm	重量 cm	重量 cm	重量 cm