2017 Volkswagen VW Polo 5HB TSI Trendline

OVERALL	EXTERIOR	INTERIOR
3.5	-	-

MODEL CODE DBA-6RCJZ	DISPLACEMENT 1,197 cc
YEAR / REG. 2017/03	MILEAGE 43,593 km
DOORS 5	SEATS 5
DRIVETRAIN 2WD (FF)	TRANSMISSION AT
FUEL Petrol	STEERING Right
EXTERIOR COLOR Other	BODY TYPE Hatchback
CHASSIS NO. WVWZZZ6RZHU041177	DIMENSIONS (L X W X H) 400 × 169 × 146 cm

SALES POINTS

Pre-Collision Braking

Navigation System

INSPECTOR REPORT

Interior: dirt, stains. Exterior: stone chips, scratches.

ORIGINAL JAPANESE AUCTION SHEET



初年度登録 H29 3月
メーカー フォルクスワーゲン
ドア枚数 5
ボディ形状 コンパクト/ハッチバック
評価点 3.5
車名 ポロ
グレード TSIトレンドライン
駆動区分 2WD 4WD
車歴 自家用 ・ その他 ( )
排気量 1190 cc
型式 DBA-6RCJZ
通称型式
内装 A ・ B ・ C
車検 8 年 8 月 抹消
燃料 ガソリン ディーゼル ハイブリッド ( )
検日渡り品 (車検証 ・ 取扱説明書 等)
走行 43,593 マイル km
シフト AT
外装色 レッド
カラーNo. (LP3G)
エアコン A:C ・ AAC ・ WAC ・ ( )
( ) 色変更は()内に「色番」を記入
内装色 その他
乗車定員 5 人
装備品のみ ○印 を記入
PS PW AW サンルーフ 革シート
エアバック ABS ナビ TV キーレス
ハンドル 左 ・ 右
輸入区分 デ ・ 並行
リサイクル料 14,270円 ・ 預託無
セールスポイント
0
修復歴 有 ・ 無
A キズ U ヘコミ・オサレ B キズ・ヘコミ P 色あせ・ボケ G ガラスキズ
W 補修跡 S サビ C 腐食 X 交換車 XX 交換所
検査記入欄
登録No. 名変中
月 日 までに名変できる方
車体番号 WVWZZZ6RZHU041177
FW トビ石 傷 ワレ 外装 小 A ・ U ホイル A ・ 曲 エアロ A ・ ワレ
シリアルNo.
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スル
車輌 長さ cm 幅 cm 高さ cm 最大積載量 0 Kg