

2017 SUBARU XV 2.0i-L EyeSight		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
GT7	1,995 cc		
YEAR / REG.	MILEAGE		
2017/11	36,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GT7-058904	447 × 180 × 160 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Adaptive Cruise Control		Cruise Control	
Navigation System			
INSPECTOR REPORT			
Interior scratches, dirt; Seat scuffs, wrinkles; Exterior small scratches, light scratches.			

初年度登録	メーカー スバル	ドア数	5	ボディ形状	SUV/クロカン	評価点	
H29 / 11月	車名 X V	グレード	2.0 i-L アイ サイト	駆動方式	2WD	4.5	
車種	自家用・その他()	排気量	2000 CC	型式	GT7	過熱式	内装 A・⑨・C
乗客	8人	燃料	ガソリン	ディーゼル		最低燃費値()	(保証年・取扱説明書等)
走行	36,000 km	材料	ハイブリッド				
外装色	ダークブルーパール	カラーNo.		エンジン	Q6・AAG・WAG・()		
		内装色		標準定員	5人		
シート	左・右(輸入別)	ディーラー	旅行	リサイクル料	11,870円	販売税	
セールスポイント							
本革シート/パワーシート/C/D/バックカメラ/E/IC/横滑り防止装置(E S C)/履転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ(A W D /アイドリングストップ/シートヒーター/D V D再生/ミュージックサーバー							
検査記入欄							
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ							
修復歴 有、⑥							
A	キズ	U	へこみ割れ	B	キズ/へこみ	P	熱影響/ゆがみ
W	錆腐蝕	E	サビ	C	変質	X	交換部
登録地							名義主
G17-058904							家まで名義者である
FW	トボ石	傷A	ワレ	外装	小キズ・⑩・⑪	ホイル	A・⑫・⑬
内装	⑭	シミ	ヤブレ	コガ	コガ	オールドイデ	⑮・⑯
車検 合格 補修 必要 廃止 最大積載量							