

2017 SUBARU XV 2.0i-S EyeSight		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GT7	DISPLACEMENT 1,995 cc		
YEAR / REG. 2017/09	MILEAGE 46,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE SUV		
CHASSIS NO. GT7-052476	DIMENSIONS (L X W X H) 447 × 180 × 160 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats have scuffs and wrinkles. Exterior has minor and light scratches. Overall AA rating is 4.5.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H29/9月	メーカー スバル	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4.5					
車名 XV	グレード 2.0i-S	駆動方式 2WD	燃費区分 4WD						
車種 自家用・その他	排気量 2000 cc	型式 GT7	通称 型式	内装 A・B・C					
車検 -年-月-日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)						
走行 46,000 km	走行 フロア	AT							
外装色 クールグレーカーキ	カラーNo. A00	エアコン	新着品のみ O印 を記入						
内装色 A00	乗車定員 5人	サンルーフ	高シート						
小・中・大 左・中・右	ディーラー 走行	11,870円	エレクトロニクス	その他					
セールスポイント									
パワーシート/CD/バックカメラ/TC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ/ワンセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/オートクルーズコントロール/DVD再生									
検査記入欄									
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4.5点仕入れ									
修理履歴									
有・無									
A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/汚れ	Q	ガラスキズ
W	雨腐跡	S	サビ	C	腐食	X	交換済	XX	交換済
売却No.					名義中				
月					日				
車体番号					GT7-052476				
FW	トランス	エンジン	フル	外装	小	ホイール	エアロ	シリアル	
内装	シロ	ヤブレ	コゲ	コゲ	オーディー	オーディー	オーディー	最大積載量	
重量	cm	cm	cm	cm	cm	cm	cm	kg	