


2018 Audi Audi A1 Sportback 1.0 TFSI		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-8XCHZ	DISPLACEMENT 999 cc		
YEAR / REG. 2018/02	MILEAGE 40,933 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. WAUZZZ8X7JB028268	DIMENSIONS (L X W X H) 399 × 174 × 143 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Light rust on underbody, minor scratches on front bumper bottom, no spare tire, medium scratches on pillar interior trim, wear on steering wheel and shift knob, paint peeling on underbody chassis plastic, light line scratches on exterior.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/2月	メーカー アウディ	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価点 4
車名 A1スポーツバック	グレード 1.0TFSI	駆動区分 2WD	4WD	
車種 自家用・その他()	排気量 1000 cc	型式 DBA-8XCHZ	塗装 内装 A・B・C	
車検 9年12月	燃料 ガソリン	ディーゼル	後日選り品(保証書・取扱説明書等)	
走行 40,933 km	マイル フロア	AT		
外装色 ブラック	カラーNo. AG・AG・WAG・()	エアコン	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	5人	サンルーフ	革シート
ボディ 左・右	輸入 国産	走行 11,850 km	エアバッグ	ABS
セールスポイント Bカメラ、ETC、スマートキー、ナビ、TV、AW (185/60R15)				
検査記入欄		修復歴 有・無		
下廻りS有、Fバンパー下面A小、スベアタイヤレス、ピラー内張傷中、ハンドルすれ、シフトノブすれ、下廻りシャシブランプ、外装うすい線キズ		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・傷 G ガラスキズ W 補修跡 S サビ C 腐食 X 交換部 XX 交換済		
登録No.		月 日 までに名義できる方		
車体番号 WAUZZZ8X7JB028268		名義中		
FW A1	シロ	フレ	外装 小	ホイール A・フレ
内装 A1	シロ	ヤブレ	コガ	オーデイオ
長さ cm	幅 cm	高さ cm	最大積載量 Kg	