

2018 Audi Q2 1.0 TFSI Sport		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ABA-GACHZ	999 cc		
YEAR / REG.	MILEAGE		
2018/09	45,479 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WAUZZZGA4JA114365	420 × 180 × 150 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			
Pet hair in interior, interior upholstery scratches, steering wheel wear			

初年度登録		メーカー アウディ		型式番号 5		国名・車種 SUV/クワカン		評価点 4	
H30 / 9月		Q 2		グレード 1.0 TFSI S ポット		駆動方式 2WD 4WD			
車種 自家用 ・ その他 ()		排気量 1000 CC		型式 ABA-GACHZ		燃費モード 普通		内装 A ・ B ・ G	
年 - - 年		月 - 月		日 - 日		総走行距離 ハイブリッド ()		ディーゼル シャフト	
走行 C/D/E/F/G/H/I/J/K/L/M/N/O/P/Q/R/S/T/U/V/W/X/Y/Z		AT		後日送り込み (保証書・取扱説明書等)					
外装色 ボワイト		カラーNo. AG・GAG・WAG・()		新着品のみ O印 を記入					
()		内装色 黒革調		人		サンルーフ 寒シート キーレス			
左・前・後 左・前・後		輸入区分 A・B・C・D・E・F・G・H・I・J・K・L・M・N・O・P・Q・R・S・T・U・V・W・X・Y・Z		走行 15,250円		エンジン・変速機・サスペンション・ブレーキ・ステアリング・タイヤ・ホイール・その他			
セールスポイント						修復歴 有 ()			
検査記入欄						A 今ズ U ヘコイサリ B キズヘン D 熱劣化・割ケ F ガスチ W 補修跡 S サビ C 腐食 X 交換部 XX 交換済			
室内動物の毛						登録地 月 日 まで名義できる			
室内内張キズ						車体番号 WAUZZZGA4J A114365			
ハンドルスレ						FW () () ワレ 外装 小 () () ホイル () () エプロ シリアム () ()			
						内装 () () シモ ヤブレ コグ コグス オープオス () ()			