

2018 BMW 1series 118d Sport		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-1S20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2018/08	MILEAGE 43,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. WBA1S520305L19319	DIMENSIONS (L X W X H) 434 × 177 × 144 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Exterior: While noticeable scratches and dents have been repaired, minor scratches and dents remain. Interior: There are some noticeable stains and dirt in certain areas. Repair history: No abnormalities in the frame.			

新年度登録		メーカー		乗用車内のグレード証/JAA/AAC証の評価に下記記載の評価は異なりません				評価点	
H30 8月		B M W		5 グレード		コンバクトハッチバック		4	
		1 シリーズ		118d Sport					
車種 自家用		ディーラー		右		LDA-1520		年式 2000	
年式 9年 8月 / 経過		走行 43,000 マイル		燃費 AC		車種 ディーゼル		車種 B	
外装色 白		カラー-No. 18,570		リサイクル料 0		納付番号 WBAS152030SL19319			
()		シフト アフロ AT		乗車人数 5人		乗車 乗車		乗車 乗車	
販売店 ()		内装色 ()		車種 ()		車種 ()		車種 ()	

9
8
43,000
0
0
0

18,570
0
0
0
0
0

WBAS152030SL19319

AT
5
AC

18,570
0
0
0
0
0

WBAS152030SL19319

AT
5
AC