

2018 BMW BMW OTHER BMW M5 4WD Comfort P All Seats Heater & F Massage White Leather ACC		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE ABA-JF44M	DISPLACEMENT 4,394 cc		
YEAR / REG. 2018/09	MILEAGE 25,213 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. WBSJF02070GA03433	DIMENSIONS (L X W X H) 496 × 190 × 148 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Adaptive Cruise Control Front Camera Back Camera Navigation System		Leather Seats Pre-Collision Braking Parking Assist (Auto Steering) Side Camera 360° Camera harman/kardon Surround Sound System	
INSPECTOR REPORT			

出 品 票		車 名		D/E型	グ レード		年 月	評 価 点																								
初年度登録 30 年	BMW		E	M5		2WD 4WD	4.5	B																								
9 月	型式	ABA JF44M	4,400 cc		燃料	ガソリン		B																								
車種	車庫	私家用		シート	FAT	冷暖	AC	装備品(禁止/除外/有) Oをつける																								
走行距離	25,334 km				メーター		PS ラビ PW 革 TV SR AW エアB ABS																									
外装色	元色	ブルー	カラーNo.	C1K	内装色			輸入車の為																								
車台No	VWHSJF02U01GA03433			キリ数			モデル年式	ディーラー																								
登録No.			リサイクル/RCSE	21,330	付随品	未確認	ハンドドル	右																								
定員	5	積載量	kg	重量	mm	橋	mm	後目録送品																								
セー ルスポイント		コンフォートDSCマサージ/アンビエントエアP/ステアリングヒーター） MxDrive 直接ACC HUD LOW																														
全席シートヒーター&前席ベンチレーション付シルバーストーンメリルレザー ソフトクローズドア 4ゾーンAC																																
液晶メーター カーボナルーフ タッチパネルナビ全周囲カメラ3Dビュー 20AW 電動トランク ワイヤレス充電																																
<table border="1"> <thead> <tr> <th>A</th> <th>左径</th> <th>U</th> <th>ハブ中心から</th> <th>B</th> <th>軸心から</th> <th>H</th> <th>軸心から</th> <th>G</th> <th>ギョウカ径</th> <th>NX</th> <th>三爪径</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>180mm</td> <td>5</td> <td>サビ</td> <td>O</td> <td>前部</td> <td>X</td> <td>後面部</td> <td>X</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>									A	左径	U	ハブ中心から	B	軸心から	H	軸心から	G	ギョウカ径	NX	三爪径	W	180mm	5	サビ	O	前部	X	後面部	X			
A	左径	U	ハブ中心から	B	軸心から	H	軸心から	G	ギョウカ径	NX	三爪径																					
W	180mm	5	サビ	O	前部	X	後面部	X																								
注意事項・不具合箇所 AIS検査済み 検査員記入欄：修理歴「有」の場合は修理箇所・交換箇所を記入																																