

2018 BMW BMW X1 xDrive 18d 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LDA-HT20	1,995 cc		
YEAR / REG.	MILEAGE		
2018/09	38,495 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Black	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAHT920005L22861	446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Power Seats (Front)		Pre-Collision Braking	
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor exterior scratches, adhesive residue on dashboard, interior dirt, interior trim scratches, minor wrinkles and scuffs on seats, window film applied.			

年式登録 H30 / 9月	メーカー BMW	ドア数 5	ボディ形状 SUV/クロカン	評価点 4
車名 X 1	グレード xDrive18d 4WD	2WD 4WD ④D		
車種 自家用・その他 ()	年式 2000 CC	型式 LDA-HT20	型式指定 ()	内装 A・B (C)
車検 - - 年 / 月 / 日	燃料 ガソリン ハイブリッド ()	モーター ()	輸送用品 (保証書・取扱説明書 等)	
走行 C10にマージン記入(※全数) ※ (走行年 年 月 日)	シフト フロア AT			
外観色 クロ	カラーNo. AC・AG・WAC・()	新車品のみ O印 を記入		
()	内装色 最新型車	5人	(P)	(P)
左・(R)	輸入区分 デュー	車行	AW	サンルーフ
	20,540円	販売店	AW	ナビ
セールスポイント		キーレス		
修復歴 有 (R)				
検査記入欄				
外装薄い線キズ、ダッシュ板のり付、室内汚れ、室内内張傷、シートしわ小、シートすれ小、ガラスフィルム張				
車検No. 月 日 名氏				
車検番号 WBAHT920005L22861				
車検No. 月 日 名氏				
車検番号 WBAHT920005L22861				
車検No. 月 日 名氏				
車検番号 WBAHT920005L22861				