


2018 BMW BMW X1 xDrive 18d xLine		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LDA-HT20	1,995 cc		
YEAR / REG.	MILEAGE		
2018/12	48,072 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAHT920X05L23404	446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Pre-Collision Braking		Parking Assist (Auto Steering)	
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor scratches and dents throughout.			

初年度登録		メーカー		BMW		ドア数		ボディ形状		SUUVクロカン		特価点											
H30 / 12月		車名		X 1		グレード		xDrive 18 d xライン		駆動方式		2WD 4WD											
車種		自動車・その他()		年式		型式		LDA-HT20		通称		内装											
乗積		- - 年 / 月 / 日		燃料		ガソリン		ハイブリッド		後日送り品 ()		取付金庫等 ()											
走行		口内にヤリや釘類入 () 左前部は11月に 「右側」を輸入		シフト		フロア 8 AT																	
外装色		ミネラルホワイト		カラーNo.		(A96)		エンジン		AD・6AO・WAG・()		新着品のみ O印 を記入											
()		内装色		標準定員		5人		EP		FP		AN											
シモ		左・右		輸入区分		G		走行		リサイクル料		20,540円・税別											
セールスポイント		ハーフレザシート シートヒーター 純HDDナビ ブルートゥース接続 クルーズコントロール ドライブアシスト パーキングアシスト PDC 電動トラック LEDヘッドライト ミラーETC ドラレコ																					
検査記入欄		有 ()		修復歴																			
各小傷小ヘコミ等		A キズ		U ヘコミやサビ		B キズへコミ		P 色あせや汚れ		G ガラスキズ		W 傷跡		S サビ		O 腐食		X 交換機		XX 交換済			
登録No.		月		日		まで任意で省略可		車検番号						MBAHT920X05L23404									
FW		()		車種		ワレ		外装		小 ()		オイル ()		エアロ ()		シリアル No.		長さ		幅		最大荷重	
内装		()		シモ		ヤブレ		コグ		コグス		オーデイズス		スレ		深さ		高さ		重量			