

2018 BMW BMW X1 xDrive 18d xLine		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LDA-HT20	1,995 cc		
YEAR / REG.	MILEAGE		
2018/09	122,798 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAHT920405L22152	446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Leather Seats		Power Seats (Front)	
Pre-Collision Braking		Parking Assist (Auto Steering)	
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor scratches on mirror, seat, door trim, pillar trim, and cargo area trim. Seats have medium wrinkles and large scuffs. Steering wheel and console have medium scuffs. Shift knob is scuffed. Rear gate trim has medium scratches. Headlight lenses are deteriorated. Interior has an air freshener scent.			

[illegible]