


2018 BMW_Mini BMW Mini Clubman Cooper SD Clubman		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LR20	1,995 cc		
YEAR / REG.	MILEAGE		
2018/12	55,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Station Wagon		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WMWLR520702H69791	427 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Back Camera		Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/12月	メーカー MINI	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 4.5
車名 MINI	グレード クーパーSD ク ラブマン AIS検査済	駆動区分 2WD 4WD		
車種 自家用・その他()	排気量 2000 cc	型式 LR20	通称 型式	内装 A・⑨・C
年 9	月 12	抹消 ガソリン	燃料 ハイブリッド()	後日取り込み(保証書・取扱説明書等)
走行 55,000 km	マイル フロア 8 AT	シフト	取扱説明書・記録簿	
外装色 メルティングシルバー	カラーNo. ()	エアコン ⑨B・AAG・WAG・()	整備品のみ O印 を記入	
内装色 ()	乗車定員 5人	⑨B	サンルーフ	革シート
左・右 左・右	輸入区分 デ	並行	19,440円・預託金	⑨B
セールスポイント バックカメラ/機滑り防止装置(ESC)/運転席エア バック/盗難防止システム/スマートキー/キーレスエント リー/ABS/助手席エアバック/サイドエアバック/HDD ナビ/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリン グストップ/ターボ/ミュージックサーバー/ミュージック プレーヤー接続可				
検査記入欄		修復歴 有・⑨		
		A キズ U ヘコみ/サレ B キズ・ヘコみ P 色あせ・ボケ Q ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換済		
		登録No. 名 変 中 月 日 までに名変できる方		
		車体番号 WMWLR520702H69791		
FW ⑨B	備A	フレ	外装 小	ホイール エアロ
内装 ヨゴレ	シミ	ヤブレ	コガ コガ穴	オーディ穴
		⑨A・⑨ A・曲 A・フレ		シリアル No.
		⑨A		長さ 幅 高さ 最大積載量 kg