

2018 BMW_Mini BMW Mini Clubman John Cooper Works Clubman		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE LVJCW	DISPLACEMENT 1,998 cc		
YEAR / REG. 2018/03	MILEAGE 47,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Station Wagon		
CHASSIS NO. WMWLV920702G35088	DIMENSIONS (L X W X H) 427 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Dinamica / Leather) Navigation System		Roof Rails Back Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/3月	メーカー MINI	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 4.5
車名 MINI	グレード ジョンクーパーワークス クラブマン AIS検査済	駆動区分 2WD	4WD	
車種 自家用・その他 ()	排気量 2000 CC	型式 LVJ CW	選装 型式	内装 A・B・C
車検 9年9月	燃料 ガソリン	ディーゼル	後日選用品 (保証書・取扱説明書 等)	
走行 47,000 km	シフト フロア 8 AT	取扱説明書・記録簿・スペアキー		
外装色 ミッドナイトブラック	カラーNo. ()	エアコン	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ	取付	ト
左・右 左・右	走行 19,440円	ナビゲーション	取付	TV
セールスポイント				
本革シート/パワーシート/バックカメラ/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/ターボシートヒーター/ミュージックサーバー/ミュージックプレイヤー接続可				
検査記入欄				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッパ P 色あせ・ボケ Q ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換済 YX 交換済				
登録No. 月 日 までに名義変更の方				
車体番号 WMWLV920702G35088				
FW トンネル 備A フレ 外装 小 ホイル エアロ A・曲 A・フレ				
内装 日ゴレ シェ ヤブレ コガ コガ穴 オーディオ				
長さ cm 高さ cm 最大積重量 Kg				