

2018 BMW_Mini BMW Mini Clubman Molton Edition		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-LR20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2018/08	MILEAGE 95,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. WMWLR920502H11637	DIMENSIONS (L X W X H) 427 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/8月	メーカー MINI	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 4.5
車名 MINI	グレード モルトン エディション 120	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 2000 CC	型式 LDA-LR20	選装 型式	内装 A・B・C
車検 9年8月	抹消 燃料 ガソリン ハイブリッド ()	シフト マイル フロア 8 AT	後付選用品 (保証書・取扱説明書 等)	
走行 95,000 km	外装色 ホワイトシルバー	カラーNo. ()	内装色 ()	乗車定員 5人
左・右 左・右	輸入 ディーラー	販売 ディーラー	19,440円	税別
セールスポイント				
キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/HDDナビ/衝突被害軽減ブレーキ/ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/LEDヘッドライト/横滑り防止装置 (ESC)/シートヒーター/ミュージックサーバー/ミュージックプレーヤー接続可/CD/バックカメラ/障害物センサー/M Tモード付き				
検査記入欄				
AA査定車				
修理歴 有・無				
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ Q ガラスキズ W 燃費劣 S ヤビ C 腐食 X 交換済 YX 交換済				
登録No. 月 日 までに名実である方				
車体番号 WMWLR920502H11637				
FW トボ石 傷A フレ 外装 小 A・U ホイル A・曲 A・フレ エアロ シリアル No.				
内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオ穴 スレ				
取組 長さ cm 幅 cm 高さ cm 最大積重量 Kg				