

2018 BMW_Mini BMW Mini Crossover Cooper D		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-YT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2018/03	MILEAGE 54,000 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Pearl White		
BODY TYPE SUV			
CHASSIS NO. WMWYT920803E82047	DIMENSIONS (L X W X H) 432 × 182 × 160 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Roof Rails Adaptive Cruise Control	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/3月	メーカー MINI	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 MINI	グレード クーパー D 女性ワンオーナー 禁煙車 純正地図ナビ	駆動区分 2WD 4WD		
車歴 自家用・その他 ()	排気量 2000 CC	型式 LDA-YT20	選装 型式	内装 A・B・C
車検 9年3月	抹消 燃料 ガソリン ハイブリッド ()	デジ ギル	後付選用品 (保証書・取扱説明書 等)	
走行 54,000 km	シフト フロア 8 AT			
外装色 ホワイトブラック	カラーNo. ()	エアコン A・AAG・WAG・()	装備品のみの O印 を記入	
内装色 ()	乗車定員 5 人	サンルーフ 革シート		
左・右 左・右	輸入 ディーラー・並行	リサイクル料 19,090 円	販売税 エコマーク	TV
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/H D D ナビ/衝突被害軽減ブレーキ/ワンオーナー/ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/L E Dヘッドライト/横滑り防止装置 (E S C) /障害物センサー/M T モード付き/定期点検記録簿				
検査記入欄				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換済 YX 交換済 登録No. 月 日 名義中 車体番号 WMWYT920803E82047 FW トボ石 傷A フレ 外装 小 A・U ホイル A・曲 A・フレ エアロ 内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオ穴 スレ				
長さ cm 高さ cm 最大積重量 Kg				