


2018 Cadillac CadillacXT5Crossover Platinum		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE ABA-C1UL	DISPLACEMENT 3,649 cc		
YEAR / REG. 2018/09	MILEAGE 78,116 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Left		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. 1GYFN9RS7JZ216679	DIMENSIONS (L X W X H) 483 × 192 × 170 cm		
SALES POINTS			
Alloy Wheels Roof Rails Power Tailgate Pre-Collision Braking Parking Assist (Auto Steering) Back Camera		Sunroof Leather Seats (Semi-aniline Full Leather) Power Seats (Front) Adaptive Cruise Control Front Camera Bose Studio Surround Sound 14-speak...	
INSPECTOR REPORT			
Dashboard lifting, interior scuffs and dirt, wheel scratches, various scratches, dents, and minor scratches.			

ORIGINAL JAPANESE AUCTION SHEET

H30 / 9月		メーカー キャデラック		ドア数 4	ボディ形状 SUV/クロカン		評価点 4																				
車名 キャデラックXT5クロスオーバー		グレード プラチナム		駆動方式 2WD		燃費 19.0																					
車種 自家用・その他 ()	排気量 3600 cc	型式 ABA-C1UL	燃料 ガソリン	変速機 AT	内装 A・B・C																						
年 2018	月 9	日 16	走行 78,116 km	カラー ブラック	ボディカラー パールブラック																						
販売店 キャデラックXT5クロスオーバー				後付選用品 (保証書・取扱説明書等)																							
価格 16,710円				納期 即日																							
セラーポイント ムーンルーフ/ベージュ内装/BOSEサウンド/ステアリングリモコン/Bluetooth/デジタルインナーミラー/シートヒーター&ベンチレーション/ヘッドアップディスプレイ/電動格納ミラー/																											
検査記入欄 ダッシュボードウキルム内スレヨゴレ/ボイルキズ/格キズ/凹キズ				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコキズ</td><td>B</td><td>キズ/ヘコキズ</td><td>P</td><td>色あせ/汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>腐食</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換</td><td>XX</td><td>交換</td> </tr> </table>				A	キズ	U	ヘコキズ	B	キズ/ヘコキズ	P	色あせ/汚れ	G	ガラスキズ	W	腐食	S	サビ	C	腐食	X	交換	XX	交換
A	キズ	U	ヘコキズ	B	キズ/ヘコキズ	P	色あせ/汚れ	G	ガラスキズ																		
W	腐食	S	サビ	C	腐食	X	交換	XX	交換																		
名義中				月 日 まで																							
1GYFN9RS7JZ216679																											
トヨタ	日産	ホンダ	スズキ	マツダ	三菱	富士重	スバル																				
内装	ボディ	シス	ヤブレ	コグ	コグ	コグ	コグ																				