

2018 Daihatsu Boon Boon 1.0 Silk G Package SA3		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-M700S	DISPLACEMENT 996 cc		
YEAR / REG. 2018/10	MILEAGE 36,325 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. M700S-0014797	DIMENSIONS (L X W X H) 368 × 166 × 152 cm		
SALES POINTS			
Alloy Wheels 360° Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Exterior has faint line scratches and minor A/U marks. Wheels have scratches. Side turn signal lens is cracked. Interior shows dirt, scuffs, scratches, burns, holes, tears, and rips. Front windshield has scratches, stone chips, cracks, and repair marks; replacement is recommended.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成30年10月	車名・グレード ブーン シルクGパッケージ SA3	2WD 4WD	評価点 (4.5)		
ディーラー・並行 モデル年式 ハンドル 左・右	型式 5BA-M700S	排気量 1000 CC	ドア 5 形状 木 定員 5人 積載 kg		
車種 自家用	シフト CAT	セールスポイント (正常に機能するものに限ります)			
車検 令和9年10月(日)	冷却 AAC	スマートキー・ETC			
走行 3万6千325 km	燃料 ガソリン	Bluetooth、フルセグTV、全周カメラ			
色 ブラウン	色替 T33/FD10	装備品 (純正品に限り○をつけてください)			
R券 8,610 円		(PS) (PW) (BS) (TB) (AW) SR ナビ TV カワ			
注意事項申告欄		新車保証書 有・無			
外装 うすい線キズ					
外装 小A・小U					
ホイール キズ					
サイドウインカー・レンズヒビ					
ナイスウオゴレスレ					
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要		A・キズ E・エクボ U・凹み W・補修跡 S・サビ C・腐食 XX・交換済			
内装 キズ・汚レ・コゲ・穴・スレ・キレ・破レ		型式指定番号 18742			
車台番号 0014797		類別区分番号 0005			
登録番号 市川 500 す 6084		新車保証書 有効			
		長さ 368 cm			
		幅 166 cm			
		高さ 152 cm			