

2018 Daihatsu Copen Copen 660 Cero		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA400K	DISPLACEMENT 658 cc		
YEAR / REG. 2018/01	MILEAGE 8,962 km		
DOORS 2	SEATS 2		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Kei		
CHASSIS NO. LA400K-0022492	DIMENSIONS (L X W X H) 339 × 147 × 128 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Exterior: minor abrasions & dents. Undercarriage: painted. Roof: wrapped. Door mirrors & wheels: scratches. Seats: worn. Interior trim & console: scratches. Steering wheel cover installed. Front glass: scratches, stone chips, cracks, repair marks, replacement required. Interior: scratches, stains, burns, holes, wear, tears, & rips.			

初度登録年月 平成30年 1月	車名・グレード コペン セロ	2WD 4WD (4.5)	評価点
ディーラー・並行 モデル年式 年	型式 DBA-LA400K	排気量 660 CC	ドア 2 形状 CP
ハンドル 左・右		定員 2人 機能 kg	外装 内装 B B
車種 自家用	シフト FAT	セールスポイント (正常に機能するものに限ります)	
車検 令和9年 2月 (日)	冷房 AAC	スマートキー・ETC ストラダSDナビ ETC2.0	
走行 万 8千 962 km	燃料 ガソリン	付属品 (純正品に限り○をつけてください) PS PW ABS T7B AW SR ナビ TV カワ	
色 シルバー	色コード S39/FP51	最新保証書 有・無	
R券 8,640 円	注意事項申告欄		
外装 小A・小U			
下廻り ベイント			
ルーフ ラッピング			
ドアミラー キズ			
ホイール キズ			
シート すれ			
内張り キズ			
コンソール キズ			
ハンドルカバー取り付け			
フロントガラス 内装	キズ・破れ (キズ) 汚れ・コゲ・穴・変色 キレ・破れ		
車台番号 0022492	A・キズ E・コゲ傷 U・凹み W・補修痕 S・サビ O・腐食 XX・交換済		
登録番号 成田 580 て 3465	型式別自動車 税 339 重量税 147 固定資産税 128		