

2018 Daihatsu Thor Thor 1.0 G_SA2		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-M900S	DISPLACEMENT 996 cc		
YEAR / REG. 2018/04	MILEAGE 35,949 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. M900S-0026133	DIMENSIONS (L X W X H) 370 × 167 × 173 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both... Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Exterior has minor scratches and dents. Wheels have medium scratches. Interior is dirty. Front glass has scratches, stone chips, cracks, repair marks, and needs replacement. Interior has scratches, medium stains, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成30年 4月	車名・グレード トール G_SA2	2WD 4WD	評価点 (5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-M900S	排気量 990 CC	ドア 5 形状 木
定員 5人	積載 kg	外装 A	内装 A
車種 自家用	シフト CAT	セールスポイント (正常に機能するものに限りです)	
車検 令和9年 4月 (日)	冷暖 AAC	スマートキー・カーパワースライドドア(両側)	
走行 3万5千949 km	燃料 ガソリン	両側オートスライドドア バックカメラ	
色 ブルー	色コード B67/FE10	諸備品 (純正品に限り○をつけてください)	
R券 9,630 円		(PS) (PW) (BS) (AB) A W	
注意事項申告欄		S R ナビ TV カワ	
外装 小A・小U		新車保証書 未日品	
ホイールCキズ		有・無	
室内 汚れ			
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要 内装 キズ・CD・コゲ・穴・スレ・キレ・破れ			
車台番号 0026133		A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
登録番号 市川 500 す 5959		型式認定番号 18438	車検区分別 0504
		全長 370 cm	全幅 167 cm
		全高 173 cm	