

2018 Daihatsu Thor X SA3		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-M900S	DISPLACEMENT 996 cc		
YEAR / REG. 2018/12	MILEAGE 37,100 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. M900S-0041562	DIMENSIONS (L X W X H) 370 × 167 × 174 cm		
SALES POINTS			
Pre-Collision Braking Navigation System		Back Camera	
INSPECTOR REPORT			
Exterior has minor imperfections (AU grade). Interior has dirt/stains.			

初年度登録	メーカー	ダイハツ		ドア枚数	5	ボディ形状	コンパクトハッチバック		評価点
H30 / 12月	車名	トール		グレード	X_SA3		駆動区分	2WD 4WD	4
車種	良薬用・その他 ()	積重量	1000 CC	型式	DBA-M900S		運転形式	AT	A・B・C
車検	9年12月 / 抹消	燃料	ガソリン	ディーゼル			検日選り貼 (保証書・取扱説明書等)		
走行	口内にマークを記入 (※交換・盗竊・火災)	シフト	ハイブリッド						
外装色	マゼンタペリーマイカメタリック	カラーNo.	エアカン	()		装備品のみ O印 を記入			
()	白車検(口内に「白車」を記入)	内装色	標準定員	5人		☐ 6P ☐ 7P ☐ AW ☐ サルーフ ☐ 革シート			
ハイル	左・右	ディーラー	並行	9,630円・預託金		☐ エアロック ☐ ABS ☐ 7P ☐ モーニング			
セールスポイント 純正ナビ/衝突安全装置/電動スライドドアドライブ コーダー 社外Bluetooth接続/ETC/ED/付ABS/横滑り防 止装置/アイドリングストップ/バックモニター/フルセグ TV									
検査記入欄 外装AU									
修正 有・無 A 型式 U ヘルスオレ B 型式ヘルス P 色あせボタ G ギラスキ W 補修 S サビ C 腐食 X 交換 Y 交換 登録No. _____ 月 _____ 日 _____ まで(各年度) 名 変 車体番号 M900S-0041562 シリアル No. _____ 車検 _____ 備 _____ 第2 _____ 最大積重量									