

2018 Honda Acty Truck SDX		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE HA9		DISPLACEMENT 656 cc	
YEAR / REG. 2018/11		MILEAGE 80,200 km	
DOORS 2		SEATS 2	
DRIVETRAIN 4WD		TRANSMISSION MT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR White		BODY TYPE Kei	
CHASSIS NO. HA9-1408548		DIMENSIONS (L X W X H) 340 × 148 × 175 cm	
INSPECTOR REPORT			
Minor exterior scratches, interior scuffs/stains, dent on lower left front pillar, front bumper distortion, stay warped.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/11月		メーカー ホンダ		ドア枚数 2	ボディ形状 軽四	評価点 3.5																				
車名 アクティトラック		グレード SDX		駆動区分 2WD	4WD																					
車歴 自家用・その他 ()	排気量 660	型式 HA9	通称 型式	内装 A・B・C																						
車検 9年1月 / 抹消	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取付説明書等)																							
走行 80,200マイル	シフト ハイブリッド	MT																								
外装色 ホワイト	カラーNo. ()	エアコン (A)・AAG・WAG・()	整備品のみ O印 を記入																							
()	内装色 ()	乗車定員 人	P	PW	AW	サンルーフ																				
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料	6,230円	預託金																				
セールスポイント MT車! 4WD!																										
検査記入欄 外装小傷・内装スレ・汚れ・左Fビラー下部凹み・Fバナー・ステータスひずみ			修復歴 有 ()																							
			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ・凹み</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>				A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・汚れ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																	
			登録No. () 名義中																							
			月 日 までに名義できる方																							
			車体 番号 HA9-1408548																							
			シリアル No. ()																							
PW	トド石	傷A	フレ	外装	小 (A)・U	ホイール (A)・曲	エアロ A・フレ																			
内装	ヨコシ	シメ	ヤブレ	コゲ	コゲ穴	オーディオ穴	シ																			
長さ	幅	高さ	最大積載量		Kg																					