

2018 Honda N-BOX CUSTOM GL Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2018/05	49,982 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1117891	340 × 148 × 179 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Drive...	
Pre-Collision Braking		Adaptive Cruise Control	
Navigation System			
INSPECTOR REPORT			
Interior dirt, stains			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/5月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4
車名 N-BOXカスタム	グレード G・Lホンダセンシング	駆動区分 2WD 4WD		
車歴 自家用・その他 ()	排気量 560 cc	型式 JF3	通称 形式	内装 A・B・C
車検 9年5月/抹消	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)	
走行 49,982 km	シフト インパネ	AT		
外装色 クリスタルブラックパール	カラーNo. QD・AAG・WAG・ ()	モテコン	装備品のみ O印 を記入	
内装色 ()	車庫定員 人	ABS	サンルーフ	車シート
左・前・後 左・前・後	ディーラー 8,110円	燃費 エブリック	ABS	エブリック
セールスポイント				
バックカメラ/ETC/横滑り防止装置 (ESC)/運転席エアバック/スマートキー/キーレスエントリー/助手席エアバック/メモリーナビ他/ワンセグTV/衝突被害軽減ブレーキ/アイドリングストップ/オートクルーズコントロール/ベンチシート				
修復歴 有・B				
検査記入欄				
A 型式 U ヘッドライト B キズ・ヘリ P 色あせ・汚れ Q ガラスキズ W 修理跡 S サイズ C 腐食 X 交換部 YX 交換部 名 査 中 月 日 までに名査できる方 車体 番号 JF3-1117891 シリアル No. 内装 トビ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ 内装 ヨゴレ シミ ヤブレ コガ コガ穴 オーディオ スレ				