


2018 Honda N-BOX CUSTOM GL Honda Sensing		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF3	DISPLACEMENT 658 cc		
YEAR / REG. 2018/04	MILEAGE 60,900 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Kei		
CHASSIS NO. JF3-1100791	DIMENSIONS (L X W X H) 340 × 148 × 179 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Power Sliding Doors (Both Sides) (Drive... Adaptive Cruise Control	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/4月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4.5
車名 N-BOXカスタム	グレード G・Lホンダセンシング KENWOOD地デジSDナビ Bカメラ ACC	駆動区分 2WD 4WD		
車種 自家用・その他()	排気量 660	型式 DBA-JF3	選装 型式	内装 A・B・C
車検 9年4月	抹消 燃料 ハイブリッド	ディーゼル インパネ	後付選用品(保証書・取扱説明書等)	
走行 60,900	マイル AT			
外装色 パール	カラーNo. AG・AG・WAG・()	装備品のみ O印 を記入		
()	内装色 標準装備	サンルーフ 革シート		
左・右 左・右	輸入 ディーラー・並行	リサイクル料 8,110円	販売税 エコマーク	その他 TV ス
セールスポイント ユーザー買取車 KENWOOD地デジSDナビ バックカメラ ACC パワースライドドア レーンキープアシスト ETC LEDヘッドライト スマートキー 純正14インチAW				
検査記入欄		修復歴 有・無		
		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 燃費劣化 S ヤビ C 腐食 X 交換部 YX 交換部		
		登録No. 月 日 までに名義である方		
		車検 番号 JF3-1100791		
FW トボ石 傷A フレ 外装 小 A・U ホイル A・曲 A・フレ エアロ		シリアル No.		
内装 ヨゴレ シネ ヤブレ コガ コガ穴 オーディオ穴 スレ		長さ cm 幅 cm 高さ cm 最大積載量 Kg		