

2018 Honda N-BOX CUSTOM GL Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF3	DISPLACEMENT 658 cc		
YEAR / REG. 2018/07	MILEAGE 61,400 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Kei		
CHASSIS NO. JF3-1133930	DIMENSIONS (L X W X H) 340 × 148 × 179 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Exterior has AU repair marks			

初年度登録		メーカー		ホンダ		ドア数		5		ボディ形状		軽四		評価点	
H30 / 7月		車名		N-BOXカスタム		グレード		G・Lホンダセンシング		駆動区分		2WD 4WD		4	
車種		良薬用・その他()		排気量		660 CC		型式		DBA-JF3		通称形式		内装 A・B・C	
車検		9年7月		抹消		燃料		ガソリン		ディーゼル		後日選り貼 (保証書・取扱説明書等)			
走行		口内にマークを記入(※交換 ※盗竊 ※火災)		シフト		ハイブリッド									
外装色		カラーNo.		エンジン		CVT									
プレミアムホワイトパール		()		GA・AAC・WAG・()								装備品のみ O印 を記入			
()		白車検(1円以内) (右側)と記入		内装色		標準定員		4人							
ハンドル		左・右		変速機		オートマチック		8,110円 + 預託金		エアロック		ABS		サドル	
セールスポイント															
純正8インチナビ/ホンダセンシング/両側電動スライドドア/車線逸脱防止支援システム/ヘッドランプLED/USBジャック/Bluetooth接続/ETC/BD付ABS/横滑り防止装置															
検査記入欄															
外装AU補修跡															
修復歴		有・無													
A	劣化	U	へこみ/凹	B	劣化/へこみ	P	劣化/ボロボロ	G	ガラス割れ						
W	経年劣化	S	錆び	C	腐食	X	交換済	XX	交換済						
登録地														名義	
														月 日 までに名義である	
車体番号		JF3-1133930													
FW	ボディ	座席	フル	外装	小	ホイール	エアロ	シリアル	No.						
					CD・UP	曲	A・フレ								
内装	ゴキ	シネ	ヤブレ	コゲ	コグク	オーデイクス	②	革張	鏡	鏡	鏡	鏡	鏡	鏡	鏡