

2018 Honda N BOX G Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2018/09	42,995 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Brown	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1154080	340 × 148 × 179 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Minor wear on driver's seat, minor A-pillar trim damage, minor exterior scratches, minor door trim damage, minor wear on steering wheel, minor stone chip on front glass.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/9月	メーカー ホンダ	ドア枚数 5	駆動方式 軽四	評価点 4
車名 N-BOX	グレード Gホンダセンシン	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 JF3	通称 軽四	内装 A・B・C
車検 9年9月	燃料 ガソリン	ディーゼル ハイブリッド ()	検出通り品 (保証書・取扱説明書 等)	
走行 42,995 km	インパネ	AT		
外装色 プレミアムアガットブラウンパール	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ ORP を記入	
()	内装色 ()	乗車定員 () 人	PS	サンルーフ
左・右 左・右	ディーラー ()	走行 ()	8,110円	ABS
セールスポイント CD/バックカメラ/ETC/横滑り防止装置 (ESC)/運転席エアバック/スマートキー/キーレスエントリー/助手席エアバック/メモリーナビ他/ワンセグTV/衝突被害軽減ブレーキ/アイドリングストップ/オートクルーズコントロール/ベンチシート/DVD再生				
検査記入欄 運転席すれく小 ビラー内張り A<小> 外装小傷有 ドア内張り A<小> ハンドルすれく小 Fガラス傷ひ石<小>				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ W 補修跡 S サビ C 腐食 X 交換車 XX 交換所				
登録No. 月 日 までに名義できる方				
車体番号 JF3-1154080				
シリアル No.				
長さ cm 幅 cm 高さ cm 最大積載量 Kg				