

2018 Honda N-BOX GL Honda Sensing		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2018/03	95,172 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Green	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1086261	340 × 148 × 179 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Minor scratches and dents on the exterior.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/3月	メーカー ホンダ	ドア枚数 5	ボディ構造 軽四	評価点 4.5
車名 N-BOX	グレード G・Lホンダセンシング	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 JF3	通称 軽四	内装 A・⑨・C
車検 - - 年 / 月	燃料 ガソリン	ディーゼル ()	後日選り品 (保証書・取扱説明書 等)	
走行 95,172 km	シフト インパネ	AT		
外装色 ブリティッシュグリーンパール	カラーNo. ()	エアコン ()	新着品のみ O印 を記入	
内装色 ()	乗車定員 4 人	AW ()	サンルーフ ()	革シート ()
左・右 左・右	ディーラー ()	走行 ()	8,110 円	エブリック ()
セールスポイント				
CD フルフラット バックカメラ ETC 後席リフト装置 (E S C) 電動ドアロック 電動アシストシステム スマートキー キーレスエントリー ABS 助手席エアバック サイドエアバック メモリーナビ ワンセグTV 衝突被害軽減ブレーキ 衝突安全ボディ アイドリングストップ ベンチシート ミュージックプレーヤー接続可				
検査記入欄				
外装小A,U				
修復歴 有・⑨				
A キズ U ヘコみ・凹み B キズ・ヘコみ P 色あせ・汚れ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換部 XX 交換済				
登録No. 月 日 までに名義できる方				
名義中				
JF3-1086261				
シリアル No.				
車重 cm				
最大積載量 kg				