

2018 Honda N-BOX GL Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2018/11	16,000 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1171382	340 × 148 × 179 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Drive...		Pre-Collision Braking	
Adaptive Cruise Control		Navigation System	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats have scuffs and wrinkles. Exterior has minor and light scratches. AA grade 4.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H30/11月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4
車名 N-BOX	グレード G・Lホンダセンシング	駆動方式 2WD	4WD	
車種 自家用・その他	排気量 660 cc	型式 JF3	燃費 25.0 km/L	内装 A・B・C
車検 9年11月	抹消 抹消	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)
走行 16,000 km	インパネ	AT		
外装色 ルナシルバメタリック	カラーNo. Qd・AAG・WAG・()	エアコン	AW	サンルーフ
内装色 ()	乗車定員 4人	CD/D	CD/D	CD/D
小売 左・右	輸入 左・右	サイズ 8,110円	重量 850kg	エンジン E16
セールスポイント				
CD/バックカメラ/ESC/横滑り防止装置(ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A・B・S/助手席エアバック/メモリーナビ/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/DVD再生/ミュージックプレイヤー/接続可				
検査記入欄				
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4点仕入れ				
修理履歴				
有・無				
A キズ U ヘコみ/サレ B キズ/ヘコみ P 色あせ/ボケ Q ガラスキズ				
W 腐蝕 S サビ C 腐食 X 交換品 YX 交換品				
登録No. 月 日 までに名義できる方				
車体番号 JF3-1171382				
FW トンネル 備A フレ 外装 小 ホイル エアロ シリアル				
内装 300 シミ ヤブレ コゲ コガサ オーディオ 24 重量 850 cm 備 重量 850 cm 最大積載量 400 kg				