

2018 Honda N BOX GL Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2018/11	30,866 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1178877	340 × 148 × 179 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Drive...		Pre-Collision Braking	
Adaptive Cruise Control		Navigation System	
INSPECTOR REPORT			
Headliner slight scuff, Driver's seat slight scuff, Door trim A slight scuff, Steering wheel slight scuff, Left front & left rear door & right quarter repair marks, Exterior line scratches, Wheel cover A.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H30 11月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4
車名 N-BOX	グレード G・Lホンダセンシング	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 JF3	燃費 A・B・C	
年 9	月 11	日 11	抹消 抹消	燃料 ガソリン
走行 30,866	マイル 30,866	インパネ	AT	後日選り品 (保証書・取扱説明書等)
外装色 ポリリファントスボーティブルメタリック	カラーNo. QD・AAG・WAG・ ()	エアコン	AW	サンルーフ
内装色 ()	乗車定員 4人	新車品のみ O印を記入	PS	PS
小 左・右	大 左・右	8,110円	エアロック	ABS
セールスポイント				
バックカメラ/ESC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/メモリーナビ他/ワンセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリグストップ/ベンチシート				
検査記入欄				
天幕りすれ<小> 運転席すれ<小> ドア内張りA<小> ハンドルすれ<小> エアコン & 左後ドア & 右後ドア修理跡 外装修理キズ ホイールカバーA				
A キズ U ヘコみ/サレ U ヘコみ/ヘコみ P 色あせ/ボケ Q ガラスキズ W 腐蝕 S サビ C 腐食 X 交換品 XX 交換済 名義中 月 日 までに名義できる方 車体番号 JF3-1178877				
FW	トドメ	フレ	外装	小
内装	シロ	ヤブレ	コガ	コガ穴
オーディオ	オーディオ	オーディオ	オーディオ	オーディオ
長さ	幅	高さ	最大積載量	kg