

2018 Honda N BOX GL Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2018/01	45,000 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1142496	340 × 148 × 179 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Drive...	
Pre-Collision Braking		Adaptive Cruise Control	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats show scuffs and wrinkles. Exterior has minor and light scratches. Vehicle was purchased with an AA rating of 4 points.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H30/1月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4					
車名 N-BOX	グレード G・Lホンダセンシング	駆動区分 2WD	4WD						
車種 自家用・その他()	排気量 660 cc	型式 JF3	燃費 18.0 km/L	内装 A・B・C					
年 9	月 7	抹消 なし	燃料 ガソリン	ディーゼル					
走行 45,000 km	インパネ	AT	後日選り品(保証書・取扱説明書等)						
外装色 モーニングミストブルーメタリック	カラーNo. Qd・AAG・WAG・()	乗車定員 4人	新車品のみ O印 を記入						
小 左・G	輸入 ディーラー	走行 8,110 km	エアロ	ナビ					
セールスポイント									
CD/バックカメラ/ESC/横滑り防止装置(ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/ワンセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/オートクルーズコントロール/ベンチシート/両側電動スライドドア									
検査記入欄									
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4点仕入れ									
修理歴 有・無									
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラス/ズレ
W	雨腐れ	S	サビ	C	腐食	X	交換済	XX	交換済
売却No.					名義中				
車体番号	JF3-1142496				月 日 までに名義できる方				
FW	トボ	傷A	フレ	外装	小	ホイール	エアロ	シリアルNo.	
内装	シロ	ヤブレ	コガ	コガス	オーディオ	取	高S	高S	最大積載量