

2018 Honda N-BOX GL Honda SENSING		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF3	DISPLACEMENT 658 cc		
YEAR / REG. 2018/11	MILEAGE 114,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Green	BODY TYPE Hatchback		
CHASSIS NO. JF3-1186994	DIMENSIONS (L X W X H) 340 × 148 × 179 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking		Power Sliding Doors (Both Sides) (Drive...	
INSPECTOR REPORT			
Interior dirt, wheel scratches, door mirror scratches, various scratches and dents with minor repairs.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/11月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクトハッチバック	駆動方式 2WD	グレード GL	ボディタイプ Honda SENSING	年式 4
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-JF3	通称 N-BOX	内装 A	色 C	燃料 ガソリン	ディーゼル
車検 - 年 - 月 / 日	走行 114,000 km	インパネ	CVT	後部座席 ハイブリッド ()	後部座席 ハイブリッド ()	後部座席 ハイブリッド ()	後部座席 ハイブリッド ()
外装色 グリーン (G547P)	カラーN (G547P)	エアコン	AW	サンルーフ	革シート	ナビ	TV
内装色 ()	乗車定員 4人	8,110円	エブリック	ABS	ナビ	TV	キーレス
セールスポイント				修復歴			
・ナビTV・Bluetooth・バックカメラ・スマートキー・パワースライドドア・レーダーブレーキサポート・ドライブレコーダー・ETC				修復歴			
★禁煙車 臭気無し(室内の状態・臭い・雰囲気等で判断していません)				修復歴			
★内装 展示できる状態に自社でクリーニング済みです★				修復歴			
特記事項				修復歴			
★創業35年「車庫19」★カーセンサー口コミ1,167件★業販も真摯に公正なお取引を心掛けます★80km/1時間の走行テスト済 (E.g. M異常なし)★情報はカーセンサーnetでも観れます				修復歴			
検査記入欄				修復歴			
【USS検査員評価】				修復歴			
・ルーム内汚れ・ホイールCPキズ・ドアミラーキズ・各キズ凹ボシユウ				修復歴			
FW	トコ	備A	ワレ	外装	小	ホイール	エアロ
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ	オーディオ	スレ
車検	cm	cm	cm	cm	cm	cm	cm