

2018 Honda N-VAN L Honda Sensing		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE JJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2018/12	MILEAGE 38,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. JJ1-3008489	DIMENSIONS (L X W X H) 340 × 148 × 195 cm		
SALES POINTS			
Pre-Collision Braking Navigation System		Adaptive Cruise Control	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior minor and light scratches. Purchased with an AA rating of 4.5 points.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H30/12月	メーカー ホンダ	ドア枚数 5	ボディ形状 バン	評価点 4.5
車名 N-VAN	グレード L・ホンダセンシング	駆動方式 2WD	4WD	
車種 自家用・その他()	排気量 660 cc	型式 JJ1	通称 型式	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	検日通り品 (保証書・取扱説明書等)	
走行 38,000 km	シフト インパネ	AT		
外装色 シルバー	カラーNo. ()	エアコン	新着品のみ O印 を記入	
()	乗車定員 4人	AW	サンルーフ	高シート
小 左・右	輸入 ディーラー	走行 7,510 km	エア パック	TV
セールスポイント CD/バックカメラ/ESC/横滑り防止装置(ESC)/運転 席エアバック/キーレスエントリー/ABS/助手席エア バック/メモリーナビ他/衝突被害軽減ブレーキ/アドリ ングストップ/両側スライド				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4.5点仕入れ				
修復歴 有・無 A キズ U ヘコみサレ B キズヘコみ P 色あせサレ Q ガラスキズ W 腐蝕跡 S サビ C 腐食 X 交換部 XX 交換済 売却No. 月 日 までに名義できる方 車体 番号 JJ1-3008489 FW 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 内装 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890 1234567890				