

2018 Honda Odyssey Absolute EX Honda Sensing		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE RC1	DISPLACEMENT 2,356 cc		
YEAR / REG. 2018/12	MILEAGE 77,000 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Station Wagon		
CHASSIS NO. 1206524	DIMENSIONS (L X W X H) 484 × 182 × 169 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Adaptive Cruise Control Front Camera Back Camera		Power Sliding Doors (Both Sides) (Both... Pre-Collision Braking Parking Assist (Auto Steering) Side Camera Navigation System	
INSPECTOR REPORT			
Various scratches, rear floor distortion			

初年度登録 H30 12月 メーカー ホンダ グレード 5 ボディタイプ ステーションワゴン 車名 オデッセイ エンジン アブソルート・EX 駆動方式 2WD 型式 RC1 変速機 4WD 排気量 A・B・C		車種 自動車・その他 () 排気量 2400 CC 型式 RC1 変速機 4WD 排気量 A・B・C	
車検 - 年 - 月 - 日 (前年10月～前年9月迄)		車検 - 年 - 月 - 日 (前年10月～前年9月迄)	
走行 77,000 km (前年10月～前年9月迄)		走行 77,000 km (前年10月～前年9月迄)	
外装色 ブルー (前年10月～前年9月迄)		外装色 ブルー (前年10月～前年9月迄)	
() 左・() 右 () 左・() 右		() 左・() 右 () 左・() 右	
セールスポイント		セールスポイント	
フリップダウンモニター 両側パワースライドドア		フリップダウンモニター 両側パワースライドドア	
検査記入欄		検査記入欄	
各キズ リアフロア歪み		各キズ リアフロア歪み	
車検番号 1206524		車検番号 1206524	
車検 1206524		車検 1206524	