


2018 Honda Step Wagon Spada Spada Honda Sensing		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RP3	DISPLACEMENT 1,496 cc		
YEAR / REG. 2018/03	MILEAGE 74,656 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. RP3-1217159	DIMENSIONS (L X W X H) 476 × 170 × 184 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Front Camera	
INSPECTOR REPORT			
Steering wheel wear, interior scratches, door mirror scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/3月	メーカー ホンダ	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価値 4.5
車名 ステップワゴンスパダ	グレード スパダホンダセンシング	駆動区分 2WD 4WD		
車歴 自用・その他 ()	排気量 1500 cc	型式 DBA-RP3	通称 形式	内装 A・⑥・C
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後日選り込み (⑥ 等・取付品等)	
走行 74,656 km	シフト AT	スペアスマートキー、記録簿		
外装色 ブラック	カラーNo. NH812P	AG・⑥・WAG・()	新着品のみ O印 を記入	
内装色 ()	乗車定員 7 人	⑤	⑥	⑦
⑧ 左・⑨ 右 ⑩ 左・⑪ 右	ディーラー ⑫ 走行	⑬ 10,230 円	⑭ エアコン	⑮ ABS
セールスポイント 9インチナビTV・フリップダウンモニター(パイオニア)、ETC、両側電動スライドドア、パイザー、フロアマット				
検査記入欄 ハンドルスレ、ルーム内キズ、ドアミラーキズ		修復歴 有・⑯		
		A キズ U ヘッドライト B キズ・ヘッド P 熱気センサー Q ガラスキズ W 修理歴 S サイズ C 腐食 X 交換部 YX 交換部 登録No. 月 日 まで(名義変更可) 車体番号 RP3-1217159		
⑰ ⑱ ⑲	⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	㊻ ㊼ ㊽ ㊾ ㊿		