

2018 LEXUS LS 500h Executive 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-GVF55	DISPLACEMENT 3,456 cc		
YEAR / REG. 2018/04	MILEAGE 105,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. GVF55-6003391	DIMENSIONS (L X W X H) 524 × 190 × 146 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Front Camera	
Side Camera		Back Camera	
360° Camera		Navigation System	
Rear Seat Entertainment (Dual 11.6-inch...		Mark Levinson Reference 3D Surround ...	
INSPECTOR REPORT			
Minor scratches on exterior, light stains on interior.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H30 4月	メーカー レクサス	ドア数 4	ボディ形状 セダン	評価点 4
車名 L S	グレード 500h エグゼクティブ 4WD レクサスフラッグシップセダン	駆動方式 2WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 3500 cc	型式 DAA-GVF55	登録区分 A・⑤・C	
車検 9年4月	扶養 扶養	燃料 ガソリン	ディーゼル	後付選用品 (保証書・取扱説明書等)
走行 105,000 km	フロア	CVT		
外装色 ブラック	カラーNo.	エアコン	⑤・AAG・WAG・ ()	新選用品のみ・O印を記入
内装色 ()	乗車定員 5人	⑤	⑥	サンルーフ
⑤	⑥	⑦	⑧	TV
⑨	⑩	⑪	⑫	⑬
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ他/衝突被害軽減ブレーキ/4WD/E T C /アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/横滑り防止装置 (ESC) /パワースhift/オートマン/シートヒーター/DVD再生/CD/フロントカメラ/サイドカメラ/バックカメラ/後席モニター/障害物センサー/M Tモード付き				
検査記入欄				
外装小傷あり 内装うす汚れ				
修理歴 有・⑥				
A キズ B ハコボケ C キズヘコ P 色あせ・汚れ Q ガラスキズ W 腐食 R サビ C 腐食 X 交換 Y 交換 Z 交換				
名義中 月 日 まで名義である方				
GVF55-6003391				
① トボ石	② 傷	③ フレ	④ 汚れ	⑤ 小
⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺				
① トボ石	② 傷	③ フレ	④ 汚れ	⑤ 小
⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺				