

2018 Lexus LS LS500 F Sport

OVERALL

4

EXTERIOR

-

INTERIOR

-

MODEL CODE

VXFA55

DISPLACEMENT

3,444 cc

YEAR / REG.

2018/09

MILEAGE

100,362 km

DOORS

4

SEATS

5

DRIVETRAIN

4WD

TRANSMISSION

AT

FUEL

Petrol

STEERING

Right

EXTERIOR COLOR

Pearl White

BODY TYPE

Sedan

CHASSIS NO.

VXFA55-6000877

DIMENSIONS (L X W X H)

524 × 190 × 146 cm

SALES POINTS

Alloy Wheels

Leather Seats (Leather, Ultrasuede)

Pre-Collision Braking

Front Camera

Back Camera

Navigation System

Sunroof

Power Seats (Front)

Adaptive Cruise Control

Side Camera

360° Camera

Lexus LS Premium Sound System (12 s...

INSPECTOR REPORT

Seat wrinkles, scuffs, some dirt/scratches inside the cabin, pet hair, minor scratches, minor dents.

ORIGINAL JAPANESE AUCTION SHEET

車種	メーカー	グレード	ボディタイプ	年式
H30	レクサス	4	セダン	9月
車名	LS	LS500 Fスポーツ	2WD	4
車体	3500 cc	VXFA55	型式	A・C
年式	9月	扶養	ディーゼル	後日選り品 (保証書・取扱説明書等)
走行	100,362 km	フロア 10 AT	エンジン	
外装色	パール	カラーNo.	エンジン	
内装色		5人	エンジン	
左・右	ディーラー	15,210円	エンジン	
セールスポイント				
本革シート/パワーシート/フルフラット/バックカメラ/横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ/フルセグTV/衝突安全ボディ/4WD/アイドリングストップ/エアロパーツ/シートヒーター/シートエアコン/電動リアゲート/ミュージックプレイヤー/接続可/全周カメラ/フロントカメラ/サイドカメラ				
検査記入欄				
シートシワ、スレ				
ルーム内一部汚れキズ、動物の毛				
小キズ、小凸				
A1-21A				
修復歴				
有・無				
A キズ B 傷 C 変色 D 変形 E 変色 F 変形 G 変色 H 変形 I 変色 J 変色 K 変色 L 変色 M 変色 N 変色 O 変色 P 変色 Q 変色 R 変色 S 変色 T 変色 U 変色 V 変色 W 変色 X 変色 Y 変色 Z 変色				
名義中				
月 日				
VXFA55-6000877				
cm cm cm kg				