

2018 Mazda Atenza Wagon 20S Proactive		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GJEFW	DISPLACEMENT 1,997 cc		
YEAR / REG. 2018/10	MILEAGE 70,300 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Station Wagon		
CHASSIS NO. GJEFW-400154	DIMENSIONS (L X W X H) 481 × 184 × 148 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Adaptive Cruise Control Side Camera Navigation System		Roof Rails Back Camera Front Camera 360° Camera	
INSPECTOR REPORT			
Exterior has minor scratches, shallow dents, and thin line scratches. Touch-up paint spots present. Right door mirror power folding malfunction. Front pillar XX / Center pillar XX. Traces of reinforcement removal/installation.			

ORIGINAL JAPANESE AUCTION SHEET

H30 / 10月		マツダ		5		ステーションワゴン		R																					
車種		アテンザワゴン		20S		フロア		プロアクティブ																					
型式		GJEFW		2WD		4WD																							
年		月		日		走行		70,300																					
燃料		ガソリン		変速機		AT		フロア 6																					
色		紺 M		内装色		ベージュ		5人																					
左		右		価格		12,540		円																					
★全方位カメラ ★純正8インチナビTV ★全車追従レーダークルーズ ★衝突軽減ブレーキ ★ブラインドスポットモニター ★ヘッドアップディスプレイ ★電子パーキングブレーキ ★オートホールド ★ETC ★19インチアルミホイール ★オートライトLEDヘッドライト																													
× 外装小傷・薄凹み・薄線傷有り × タッチペン箇所有り × 右ドアミラー・規格不良 × フロントピラー-XX/センターピラー-XX × ホースメント脱着跡 <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>腐食跡</td><td>S</td><td>サビ</td><td>C</td><td>変色</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>										A	キズ	U	ヘコみ	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ	W	腐食跡	S	サビ	C	変色	X	交換済	XX	交換済
A	キズ	U	ヘコみ	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ																				
W	腐食跡	S	サビ	C	変色	X	交換済	XX	交換済																				
車検 GJEFW-400154 名義中 月 日 まで 名義で販売																													
内装 フロア シロ ヤシロ コガ コガ オーディー スレ 車検 cm cm cm kg																													