

2018 MAZDA Carol 5D GL		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HB36S		DISPLACEMENT 658 cc	
YEAR / REG. 2018/05		MILEAGE 27,000 km	
DOORS 5		SEATS 4	
TRANSMISSION AT		FUEL Petrol	
STEERING Right		EXTERIOR COLOR Blue	
BODY TYPE Kei			
CHASSIS NO. HB36S-222356		DIMENSIONS (L X W X H) 340 × 148 × 148 cm	
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats show scuffs and wrinkles. Exterior has minor and light scratches. Vehicle was acquired with an AA rating of 4 points.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H30/5月		メーカー マツダ 車名 キャロル		ドア枚数 5	駆動方式 軽四	評価点 4																				
グレード GL		駆動区分 2WD 4WD																								
車種 自家用・その他()	排気量 660	型式 HB36S	通称 軽四	内装 A・B・C																						
燃料 ガソリン	ディーゼル	検印選り込み(保証書・取扱説明書等)																								
走行 27,000	マイル 43,840	インパネ	AT																							
外装色 フィズブルーパールメタリック	カラーNo. ()	エンジン Qb・AAG・WAG・()	装備品のみ O印 を記入																							
内装色 ()	乗車定員 4人	PS	AW	サンルーフ	革シート																					
左・右 左・右	ディーラー・並行	7,220円・預託金	エブリック	ABS	TV																					
セールスポイント																										
機滑り防止装置(ESC)/運転席エアバック/盗難防止システム/キーレスエントリー/ABS/助手席エアバック/メモリーナビ他/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/シートヒーター																										
検査記入欄																										
内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ AA評価4点仕入れ																										
<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘコみサレ</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・ボケ</td><td>Q</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table>							A	キズ	U	ヘコみサレ	B	キズ・ヘコミ	P	色あせ・ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみサレ	B	キズ・ヘコミ	P	色あせ・ボケ	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No. 月 日 までにも売れる方																										
車体番号 HB36S-222356																										
シリアルNo.																										
車種 長さ cm 幅 cm 高さ cm 最大積載量 Kg																										