

2018 Mazda CX-3 XD L Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DK8FW	DISPLACEMENT 1,756 cc		
YEAR / REG. 2018/08	MILEAGE 84,545 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE SUV		
CHASSIS NO. DK8FW-101062	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Leather Seats (Leather) Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/8月	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 CX-3	グレード XD Lパッケージ	駆動区分 2WD 4WD		
車種 自家用・その他()	排気量 1800 CC	型式 DK8FW	選装 型式	内装 A・B・C
車検 9年8月	抹消 燃料 ガソリン ハイブリッド()	シフト デシメル	後付選用品(保証書・取扱説明書等)	
走行 84,545 km	フロア 6 AT			
外装色 セラミックメタリック	カラーNo. 47A	エアコン Qd・AAG・WAG・()	装備品のみ O印 を記入	
()	内装色	乗車定員 5人	サンルーフ 車中泊	
左・右 左・右	輸入 区分	ディーラー ・ 銀行	リサイクル料 10,830円	販売税 エコマーク
セールスポイント 純正ナビ フルセグBluetooth バックカメラ 衝突軽減ブレーキ・キルンアシスト レーダー・クルーズコントロール ヘッドアップディスプレイ クリアランスソナー ブラインドスポットモニター		修復歴 有・無		
検査記入欄		A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ Q ガラスキズ W 燃費計 S ヤビ C 腐食 X 交換機 YX 交換機		
外装線傷		登録No. 月 日 までに名実である方 車体番号 DK8FW-101062 シリアル No.		
FW トンネル	ワレ	外装 小	ホイール	エアロ
内装	コグ	コグ穴	オーディオ穴	スレ
長さ cm		高さ cm		最大積重量 Kg