

2018 Mazda CX-3 XD Proactive Diesel Turbo		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-DK5FW	DISPLACEMENT 1,498 cc		
YEAR / REG. 2018/02	MILEAGE 54,730 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Station Wagon		
CHASSIS NO. DK5FW-210185	DIMENSIONS (L X W X H) 427 × 176 × 155 cm		
SALES POINTS			
Alloy Wheels Back Camera Navigation System		Pre-Collision Braking Adaptive Cruise Control	
INSPECTOR REPORT			
Front glass stone chip, seat scuffs, steering wheel scuffs, right C-pillar lower part B, right door mirror cover scratch.			

ORIGINAL JAPANESE AUCTION SHEET

H30/2月		マツダ		5		ステーションワゴン		3																																																			
C X-3		XDプロアクティブディーゼルトーボ		4WD																																																							
車種	乗用車・その他 ()	排気量	1500 cc	型式	LDA-DK5FW	通称		内装	A・B・C																																																		
車検	- - 年 月	燃料	ガソリン	変速機	オートマ	登録番号 (保証書・取扱説明書 等)																																																					
走行	54,730 km	フロア	フロア 6 AT																																																								
外装色	グレー	カラーNo.	42S	エンジン	AG・AGD・WAG ()	装備品のみ O印 を記入																																																					
内装色	()	乗車定員	5 人	サドル	○	サンルーフ	○	シート	○																																																		
走行	11,010 km	リサイクル料	11,010円	エコマーク	○	○	○	○	○																																																		
セールスポイント																																																											
検査記入欄		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘッドライト</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ・汚れ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>修理跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> <tr> <td colspan="10">名義中</td> </tr> <tr> <td colspan="10">月 日 までに名義できる方</td> </tr> <tr> <td colspan="10">登録番号 DK5FW-210185</td> </tr> </table>								A	キズ	U	ヘッドライト	B	キズ・へこみ	P	色あせ・汚れ	Q	ガラスキズ	W	修理跡	S	サビ	C	腐食	X	交換済	XX	交換済	名義中										月 日 までに名義できる方										登録番号 DK5FW-210185									
A	キズ	U	ヘッドライト	B	キズ・へこみ	P	色あせ・汚れ	Q	ガラスキズ																																																		
W	修理跡	S	サビ	C	腐食	X	交換済	XX	交換済																																																		
名義中																																																											
月 日 までに名義できる方																																																											
登録番号 DK5FW-210185																																																											
F ガラス飛び石 シート擦れ ハンドル擦れ 右Cピラー下部B 右ドアミラーカバーキズ		<table border="1"> <tr> <td>内装</td><td>シロ</td><td>ヤブ</td><td>コガ</td><td>コガ</td><td>オーディ</td><td>オーディ</td><td>オーディ</td><td>オーディ</td><td>オーディ</td> </tr> <tr> <td>427</td><td>176</td><td>155</td><td colspan="7">最大積載量 kg</td> </tr> </table>								内装	シロ	ヤブ	コガ	コガ	オーディ	オーディ	オーディ	オーディ	オーディ	427	176	155	最大積載量 kg																																				
内装	シロ	ヤブ	コガ	コガ	オーディ	オーディ	オーディ	オーディ	オーディ																																																		
427	176	155	最大積載量 kg																																																								