

2018 Mazda CX-5 2.2 XD L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KF2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/09	MILEAGE 57,957 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Other		
BODY TYPE Other			
CHASSIS NO. KF2P-215958	DIMENSIONS (L X W X H) 454 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Side Camera Navigation System		Leather Seats Cruise Control Back Camera	
INSPECTOR REPORT			
Light interior dirt, console scratches, seat wear, minor mirror damage, steering wheel scuffs, door trim scratches			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号	18797	車両識別番号	0002	シリアル番号		評価点	
年式	車名	グレード	駆動	評価点					
H 30	CX-5	2.2 XD Lpkg	5	4					
9月	型式	3DA-KF2P	排気量	2,200 cc	燃料	ガソリン	内装	A	C
車種	R 09	9月	車況	自家用	シフト	AT	変速	AC	
走行距離	57,957 km	マイル	8	+	0	(不明)	純正ナビ	SR	
外観色	ソニックブルーメタリック	色替無	カラーNo.		内装色		純正AW	エアB	
車台No.	KF2P-215958	名義	月	日	ナビ機能	(社外品含む) ○をつける	フルセグ	CD	アナログ
登録No.	沖縄 333 と	2018	リサイクル	12,570円	未納税		HDD	DVD	SD
定価	5 ()	種別	kg	454	184	169	DVD再生可	CD	
輸入車のみ	モダ	生	輸入国	ディーラー	認定	ハンドル	左	新車保証書	車検取得
セーレスポイント	BOSEサウンドシステム 禁煙車 純正ナビ 360°カメラ 地デジ レザーシート シートヒーター								
ター									
注意事項・不具合箇所									
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入									
室内汚損									
コンソール傷									
シートヘタリ									
ミラーA									
ハンドルスレ									
ドア内傷									
ドアミラー	キズ	ヒビ	ウレ						
1点	無	シヤシキ	無						