

2018 Mazda CX-5 25S L Package		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE KF5P	DISPLACEMENT 2,488 cc		
YEAR / REG. 2018/12	MILEAGE 40,006 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE SUV		
CHASSIS NO. KF5P-301809	DIMENSIONS (L X W X H) 455 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Pre-Collision Braking Side Camera Front Camera Bose Sound System (AUDIOPILOT2 + C...		Leather Seats Power Seats (Front) Adaptive Cruise Control Back Camera Navigation System	
INSPECTOR REPORT			
Left front fender stay XX (bolt), left rear fender XX, interior dirt and scratches, door mirror scratches, small scratches and dents.			

初年度登録		メーカー		ドア数		SUUV/クロカン		駆動形式	
H30 / 12月		マツダ C X-5		5		2セス 5ケジ		Lパッ	
		車名		グレード		燃費表示		9.8W 2WD 4WD	
車種		用途用・その他()		排気量		型式		内装	
乗員		3人		3500		CC		KF5P	
走行		燃料		ディーゼル		後付選付品		(保証書・取扱説明書等)	
燃料		ガソリン		ハイブリッド					
走行		シフト		フロア 6 AT					
外観色		カラーNo.		AD・GND・WAC・()		新着商品のO印を記入			
()		内装色		標準定価		5人			
左・右・前・後		ディーラー		走行距離		12,340 km		燃費	
セールスポイント		黒革 ナビTV Bluetooth 電動リアゲート ステアリングヒーター 全周囲カメラ ETC シー トヒーター							
検査記入欄		F左フエンダーステーXX(ボルト) R左フエンダーXX ルーム内流れキズ ドアミラーキズ 小キズ小凹							
修復歴		有、⑤							
A キズ		U ハンぺオヤリ		B キズヘンタ		D 鉄板変形		E ガラスキズ	
W 傷跡		S キズ		C 腐食		X 交換済		XX 交換済	
登録地		月		日		家でどこに名義できるか			
車体番号		KF5P-301809							
FW		①		フレ		小		エアロ	
内装		②		シロ		サブル		コグ	
		コグ		コグ		オーデイオ		最大積載量	