

2018 MAZDA CX-5 25S_L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
6BA-KF5P	2,488 cc		
YEAR / REG.	MILEAGE		
2018/06	60,900 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
KF5P-202924	455 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels		Leather Seats (Perforated Leather)	
Power Tailgate		Power Seats (Front)	
Pre-Collision Braking		Adaptive Cruise Control	
Side Camera		Back Camera	
Navigation System			
INSPECTOR REPORT			
Exterior AU			

初年度登録		メーカー マツダ		ドア数 5		ボディ形式 SUV/クロカン		駆動方式 後輪駆動		年式 平成 4																																					
H30 / 6月		車名 C X - 5		グレード 25S_Lパッケージ		燃費区分 2WD 4WD																																									
車種 自動車用 ・ その他 ()		排気量 2500		型式 CC		58A-KF5P		運転形式		所属 A・B・C																																					
車検 9 年 6 月 / 抜消		燃料 ガソリン		ディーゼル		後付選り品 (保証書・取扱説明書等)																																									
走行 10万km / 60,900		シフト オート		AT																																											
外装色 カラーNo.		エンジン QD・AAO・WAD・()		新着商品の O印 を記入																																											
ジェットバックマイカ ()		標準定員 5人		オプション ① ② ③ サンプル オート																																											
左・前・右 ディーラー・運行		リサイクル料 12,570円		エコパック ④ ⑤ ⑥ ⑦ ⑧																																											
セールスポイント																																															
純正ナビ/衝突安全装置/シートヒーター/車線逸脱防止支援システム/シート フルレザー/電動バックドア/パッドパングLED/ETC/E BD付ABS/横滑り防止装置																																															
検査記入欄																																															
外装AU																																															
検査履歴 有、 G																																															
<table border="1"> <thead> <tr> <th>A</th> <th>B</th> <th>C</th> <th>D</th> <th>E</th> <th>F</th> <th>G</th> <th>H</th> <th>I</th> <th>J</th> <th>K</th> <th>L</th> </tr> </thead> <tbody> <tr> <td>キズ</td> <td>U</td> <td>ヘコみ/凹み</td> <td>B</td> <td>キズ/ヘコみ</td> <td>P</td> <td>ぬれ/シミ/汚れ</td> <td>Q</td> <td>ガラス/窓</td> <td>R</td> <td>タイヤ</td> <td>S</td> </tr> <tr> <td>傷</td> <td>擦</td> <td>ヤビ</td> <td>C</td> <td>変色</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>												A	B	C	D	E	F	G	H	I	J	K	L	キズ	U	ヘコみ/凹み	B	キズ/ヘコみ	P	ぬれ/シミ/汚れ	Q	ガラス/窓	R	タイヤ	S	傷	擦	ヤビ	C	変色	X	交換済	XX	交換済			
A	B	C	D	E	F	G	H	I	J	K	L																																				
キズ	U	ヘコみ/凹み	B	キズ/ヘコみ	P	ぬれ/シミ/汚れ	Q	ガラス/窓	R	タイヤ	S																																				
傷	擦	ヤビ	C	変色	X	交換済	XX	交換済																																							
登録年月日 月 日 所在地に当てはまる																																															
車体番号 KF5P-202924																																															
<table border="1"> <thead> <tr> <th>FW</th> <th>小</th> <th>オイル</th> <th>エアロ</th> </tr> </thead> <tbody> <tr> <td>⑨</td> <td>⑩</td> <td>⑪</td> <td>⑫</td> </tr> </tbody> </table>												FW	小	オイル	エアロ	⑨	⑩	⑪	⑫																												
FW	小	オイル	エアロ																																												
⑨	⑩	⑪	⑫																																												
内装 ⑬ シェル ⑭ ヌー ⑮ コグ ⑯ コグ ⑰ オーディエス ⑱																																															