

2018 MAZDA CX-5 Diesel XD PROACTIVE		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KF2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/03	MILEAGE 89,000 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Hatchback			
CHASSIS NO. KF2P-205592	DIMENSIONS (L X W X H) 455 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels Cruise Control Back Camera		Pre-Collision Braking Side Camera Navigation System	
INSPECTOR REPORT			
Driver's seat minor scuff, medium scuff around shift area, medium scuff on steering wheel, left side dent repair marks, front bumper bottom dent and minor scratch, front glass medium stone chip/scratch.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H30 3月	メーカー マツダ 車名 CX-5	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
グレード ディーゼルXD PROACTIVE ワンオーナーレーダー クルーズコントロール	駆動方式 2WD 4WD	型式 3DA-KF2P	内装 A・⑤・C	
車種 自家用・その他()	排気量 2188 cc	燃料 ガソリン	検定区分 2WD 4WD	
車検 - - 年 / 月 / 日	燃料 ハイブリッド()	シフト フロア	AT	
走行 89,000 km	マイล์ 000	カラーNo. スノーフレックホワイトパールAMC	エンジン QD・AAG・WAG・()	
外装色 ()	内装色 ()	乗車定員 5人	PS PW ④	サンルーフ 革シート
左・() 右・()	ディーラー 直行	15,000円	エレクトロニクス ④	TV ④
セールスポイント				
検査記入欄		A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損		
運転席すく<車前20%> シフト回りすく<中> ハンドルすく<中> 左側前220%修理済 Fバンパー下車前220%>A<車前20%> Fガラス車前221%>車前214%>中>		名義中 月 日 まで KF2P-205592		
内装 ④		シロ ④		