

2018 MAZDA CX-5 XD L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KF2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/03	MILEAGE 75,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. KF2P-205878	DIMENSIONS (L X W X H) 455 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Pre-Collision Braking Side Camera Navigation System		Leather Seats (Perforated Leather) Power Seats (Front) Adaptive Cruise Control Back Camera	
INSPECTOR REPORT			
Interior scuffs, minor scratches and dents, left and right power folding mirrors faulty			

ORIGINAL JAPANESE AUCTION SHEET

H30 / 3月		メーカー マツダ		ドア数 5		ボディ形状 SUV/クロカン		評価点 4	
車名 CX-5		グレード XD Lパッケージ		駆動方式 4WD		内装 A・⑤・C			
車種 自家用・その他 ()	排気量 2200 cc	型式 3DA-KF2P	燃料 ガソリン	変速方式 自動	乗車人数 5人	後付選用品 (保証書・取扱説明書等)			
年 月 日	走行 75,000 km	メイル フロア	変速方式 AT						
外装色 ブラック	カラーNo. 41W	エアコン AG・⑤・WAG・()	新選用品のみ O印 を記入						
内装色 ()	乗車人数 5人	⑤	⑥	⑦	⑧	⑨	⑩	⑪	⑫
⑬	⑭	⑮	⑯	⑰	⑱	⑲	⑳	㉑	㉒
左・⑳ 輸入車		ディーラー・直行		12,570円		⑳			
セールスポイント 黒革 マツダ コードレス BSMレーダー・クルーズ・レーンアシスト・パドル・ブレーキ・センサー 前後座席・ヒーター・パドル・シート・メモリー・スライド・ヒーター・CD・DVDデッキ 純正19インチAW ETC									
検査記入欄 ルーム内スレ 小キズ小凹 左右電格ミラー不良									
修復歴 有・⑥									
車検 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿									
車検 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿									
車検 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿									