

2018 MAZDA CX-5 XD L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-KF2P	2,188 cc		
YEAR / REG.	MILEAGE		
2018/12	82,000 km		
DOORS	SEATS		
5	5		
TRANSMISSION	FUEL		
AT	Diesel		
STEERING	EXTERIOR COLOR		
Right	Other		
BODY TYPE			
SUV			
CHASSIS NO.	DIMENSIONS (L X W X H)		
KF2P-304551	455 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Tailgate		Power Seats (Front)	
Pre-Collision Braking		Side Camera	
Back Camera		Adaptive Cruise Control	
Front Camera		360° Camera	
Navigation System			
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some noticeable stains and dirt are present in parts. Repair history: No abnormalities in the frame structure.			

[illegible]