

2018 Mazda CX-5 XD Proactive		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE KF2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/03	MILEAGE 40,427 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Gray		
BODY TYPE SUV			
CHASSIS NO. KF2P-200279	DIMENSIONS (L X W X H) 455 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Back Camera 360° Camera		Pre-Collision Braking Side Camera Front Camera Navigation System	
INSPECTOR REPORT			
Left and right instrument panel distortion, Right front side member bodywork and paint, Exterior linear scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H30 3月	メーカー マツダ	ドア数 5	ボディ形状 SUV/クロカン	評価点 R
車名 CX-5	グレード XD タイプ フロアク	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 2200 cc	型式 KF2P	登録区分 A・⑤・C	
走行 40,427 km	燃料 ガソリン	変速機 フロア 6 AT	後付選用品 (保証書・取扱説明書等)	
外装色 マシニンググレープレミアムメタリック	カラーNo. 46G	エアコン ④⑤・AAG・WAG・()	新選用品のみ・O印を記入	
内装色 ()	乗車定員 5人	⑥⑦⑧⑨⑩⑪⑫⑬⑭⑮⑯⑰⑱⑲⑳㉑㉒㉓㉔㉕㉖㉗㉘㉙㉚㉛㉜㉝㉞㉟㊱㊲㊳㊴㊵㊶㊷㊸㊹㊺	サンルーフ	革シート
左・()	ディーラー・直付	12,570円	①②③④⑤⑥⑦⑧⑨⑩⑪⑫⑬⑭⑮⑯⑰⑱⑲⑳㉑㉒㉓㉔㉕㉖㉗㉘㉙㉚㉛㉜㉝㉞㉟㊱㊲㊳㊴㊵㊶㊷㊸㊹㊺	①②③④⑤⑥⑦⑧⑨⑩⑪⑫⑬⑭⑮⑯⑰⑱⑲⑳㉑㉒㉓㉔㉕㉖㉗㉘㉙㉚㉛㉜㉝㉞㉟㊱㊲㊳㊴㊵㊶㊷㊸㊹㊺
セールスポイント				
純正ナビ フルセグBluetooth 全方位カメラ 衝突軽減ブレーキ/レーンアシスト クリアランスソナー ブラインドスポットモニター ヘッドアップディスプレイ				
検査記入欄				
左右インパネ歪 右FサイドメンバーBP 外装線傷				
A 欠損 B へこみ/凹み C 傷/擦り傷 D 変色 E 汚れ F 錆 G ガラス欠損 H 樹脂破損 I 塗装剥離 J 変形 K 変色 L 変色 M 変色 N 変色 O 変色 P 変色 Q 変色 R 変色 S 変色 T 変色 U 変色 V 変色 W 変色 X 変色 Y 変色 Z 変色				
登録年月日 月 日 年				
車検番号 KF2P-200279				
車検有効期限 月 日 年				
車検費用 円				