

2018 Mazda CX-8 2.2 XD L Package 6-Seater		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/06	MILEAGE 89,689 km		
DOORS 5	SEATS 6		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Other		
BODY TYPE Other			
CHASSIS NO. KG2P-121373	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Side Camera Adaptive Cruise Control Navigation System		Leather Seats Cruise Control Back Camera 360° Camera	
INSPECTOR REPORT			
Light scratches on exterior, underbody minor rust/wear, seat wrinkles, interior dirt and animal hair, interior trim scratches, light dirt on headliner.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号 18723	車両識別番号 0005	シリアル番号	評価点
年式 H 30 6月	車名 CX-8	5人	2.2 XD Lpkg 6人	4WD	4
型式 3DA-KG2P	排気量 2,200 cc	燃料 ガソリン			
車種 乗用車	用途 自家用	シフト AT	変速機 AC	純正装備品 ○をつける	
走行距離 8万9千689 km	マイル (交換) (改ざん) (不明)	カラーNo. 色替無	内装色 白	純正ナビ SR	
外装色 メーテリヤライトベージュ	色替無	車体No. KG2P-121373	名義 個人	純正AW エアホ	
登録No. 抹消	リサイクル 12,860円税込済	未納税		TV機能 (注外品含む) ○をつける	
定員 6人	重量 kg	490	184	173	
輸入車のみ モダリ 形式	輸入国 ドイツ	ディーラー 取付	ハンドル 左	新車保証書	車検取得
セーレスポイント					
純正ナビ 全周周知 360°カメラ レーダーセンサー 衝突被害軽減ブレーキ 黒革シート シートヒーター					

注意事項・不具合箇所 検査員記入欄：修理歴「有」の場合は修理箇所・交換箇所を記入 外装薄い線キズ 下廻りAU シートシワ 室内汚れ、動物の毛 室内内張傷 天張薄汚れ	
---	--

ドアミラー	ナビ	ヒビ	ウレ
1点	無	シヤシキ	無